

Basic Elements of Machining

- work piece
- Tool
- Chip
- Cutting fluid

* Free cutting either the metallic surface of the tool & work piece are unnecessary. This relative motion of the tool & the work piece is maintained by either keeping the work stationary & moving the tool or by keeping the tool stationary & moving the work by either of these methods.


* General & physical properties of work material have significant effect on the cutting operation.

* Similarly, tool material & geometry are equally imp. for better machining.

* Mechanical properties and sort of cutting fluid also provide considerable influence over the machining operation.



Orthogonal & Oblique Cutting



Orthogonal cutting (2-D)



Oblique cutting (3-D)

* The process of cutting is divided into following two main categories -

- 1) Orthogonal, 2) Oblique cutting.

1) Basically in orthogonal cutting the cutting edge of the tool, sending at right angle to the direction of the cutting velocity. This type of cutting is also known as zero cutting.

2) In oblique cutting edge of the tool is inclined at an acute angle with the direction of the tool feed. This is also known as 3-D cutting.

Classification of cutting tool


(A) Single point cutting tool

→ These shaving are one cutting edge such as lathe tool, shaper, planer etc.

* These shaving are strong one cutting edge as called multipoint such as milling tool, grinding wheel, latching etc.

(B) Multipoint cutting tool

① Single point cutting tool is



It forms the main body of the tool. It is held by the tool holder.

* Face - top surface of the tool when cut and the cutting point of the tool.

So cutting action takes place along the face.

* Cutting point - it is the upper shaped portion, where face & flank of the tool meet. It is some times called as nose and it is cutting part of the tool.

Flank - Bottom of the tool where face & the work piece to be cut are joined.

Base - It is actually lower surface of the tool on which it is held.

Heel - It is the curved portion at the bottom of the tool when this base & flank meet.

Nose radius - At this cutting process for the stress (understanding more like strength of the cutting type is increased).

It is also increased the tool life.

Rake angle is angle between the tool and the work piece.

It is measured towards the work piece and when it is measured towards the tool holder.

The rule of the tool when it is called with speed.

If guide the chip then no produces the chip lips pressure on the face.

An increase in rake angle will produce the strength of the cutting edge. So in thinning cutting process zero rake & negative rake is also provided.

* Chip angle :- Angle b/w face and flank is known as chip angle. Larger the chip angle stronger will be cutting edge.

* Clearance angle :- (cut relief angle) It is the angle formed by the front end side of surface of the tool which are adjacent to and below the cutting edge when the tool is held in its normal position. The purpose of clearance angle is to prevent the rubbing of the work surface against the surface of the job.

* Relief angle :- It is angle formed b/w the flank of the tool and perpendicular line drawn from the cutting edge point to the base of the tool.

* Tool Material :- Properties required :-

1) - Red on hot hardness :- It is a ability to withstand getting cutting edge. The steel heat treatment of tool material can be increased by adding vanadium, tungsten, molybdenum etc. All these make harder.

2) - Toughness :- It should be high for impact loading.

3) - Tool temperature :- It is tool material must be able to resist wear due to adhesion & abrasion.

4) - Low friction :-

- 1) - low coeff. of thermal expansion :-
- 2) - Good thermal conductivity -> (transfer heat)
- 3) - High specific heat (less increase in temp. during heat treatment)

* Common Material for tool

1) Carbon steel :- medium Carbon & low carbon steel

2) H.S.S :- It is used for making cutting tool which is used for cutting at high speed. H.S.S are generally of two types

- 1) M series (Machinable type or steel)
- 2) T-series (Tungsten type 11-18% content) Tm in

turning → 15%
Turning → 4%
Revolutions → 17%

15-4-1 is the extensively used HSS for cutting tool in which Dispersion is 18% Cobalt 4% and Carbides is 1%.

M. Nitro generally have high efficiency resistance than T-nitro.

Hardness of HSS falls rapidly beyond the 650°C and thus they are limited to cutting speed of 30-50 m/min. Cheap in cost.

③ Stellite :- It is a non-ferrous alloy containing cobalt (50-55%), vanium (30-35%), molybdenum & niobium. These are produced by sintering and used for gears tool.

Properties are intermediate of HSS & carbide but they are not as tough as HSS and it is resistive to impact load it retain hardness upto 600°C & used for cutting at speed upto 50m/min.

* Sintered Carbide (Cermet) :-

any comment

10/1/17

④ * Sintered Carbide :- These are made up of powder metallurgy in which mixture of tungsten, titanium, tantalum are mixed with carbide to form carbide.

The carbide in powder form are then mixed with coalt which act as binders. Then this sintered mixture is heated over 1500°C and the result of this they are sintered into desired shape & form of tools.

These carbide tips are placed on metallic body fastened to the work which is made up of melting carbon steel this provides an excellent combination of extra hard cutting edge with a tough body of steel.

It retain hardness up to one thousand or degree centigrade & it can cut at the speed of 60m/min to 300m/min.

⑤ * Ceramic or Sintered Oxide :-

The sintered consist of Al₂O₃ added with silicon carbide, magnesium oxide, zirconium oxide, titanium carbide, etc.

Ceramic tool can't machine because of the high temp the compound present it have strong affinity to tool material so growth of chips chemical reaction may take place.

any comment

These tools are not stressed but stamped. It retains hardness upto the temp. 400°C. A speed of cutting is around 600-650 m/min.

* Obtained :- It is hardest non-metallic & it has good thermal conductivity & low friction but costly.

It is not used for machine steel because of its cost as well as chemical properties. alloyed transformation into graphite on interaction with iron at 720°C temp.

In industry artificial diamonds are used.

* Graphite :-

Structure but when it is heated under high pressure it converts into carbon which is very hard structure.

It is not a natural material used it is produced in lab by heating a layer of poly-crystalline silicon carbide.

It is used for machining stainless steel at high speed (600-700 m/min).

Some times it is also used as abrasive material for grinding wheel for grinding very hard material.

* Sialon :-

* Sialon :- Sialon is a mixture of silicon material with aluminium & oxygen.

These steel have good toughness & hardness compare to conventional steels.

Due to chemical affinity of iron it is not used for machining steel. It produces excellent surface finish. But it is also costly.

* DCON :- It is practical by selling and used for machining at very speed & feed. It consist of $\text{Fe} - 80\%$, $\text{Ti} - 20\%$, $\text{Ti} - 80\%$, $\text{Ti} - 20\%$.

* Cutting Speed, Feed, Depth of Cut.

* Cutting Speed :- It is defined as the rate at which its cutting edge of the tool passes over the surface of work in unit time generally is expressed by meter/min.

It's very imp. as it affects the tool life & efficiency of machining.

If it is to high the tool get over heated and its cutting edge may fail. It is case would be need of re-grinding.

If it is too slow it will take to much time in machining which results in lower productivity & will increase the cost.

* Feed :-

Feed is the distance of cutting tool advanced in one revolution of cutting tool perpendicular to the cutting speed direction.

It is expressed in mm/revolution or mm/stroke.

* Feed rate is decided on the following factors -
- Smoothness of finishing required
- Power available
- Type of cut
- Type of tool
- Depth of cut

* Depth of Cut :- It is the thickness of layer of metal removed in perpendicular direction to the machine surface.

Depth of cut is always perpendicular to direction of feed motion.

* Machinability :-

It is defined as the ease with which a given material can be cut by finishing. The removal of material with tools partially finished at lower cost.

→ Good machinability is associated with:-

- high cutting speed
- lower power consumption
- good surface finish

For exple:- excellent machine tools

eg, M, 2m, alloys
val - maintenance -
Stellite, white cast iron

Lathe

A lathe can be defined as machine tool which hold the workpiece up in a strong axial and a stationary cutting tool against the rotating work to perform various type of cutting operation.

Lathe is also known as mother of machine tool. And engine lathe is most basic and simple form of lathe.

* Types of lathe :-

Lathe are categorized in variety of types & sizes. The different types of lathe are -

- ① Spool lathe, ② Bench lathe, ③ Engine lathe
- ④ Tool room lathe, ⑤ Turret and gear lathe
- ⑥ Special purpose lathe, ⑦ Automatic lathe.

A 98E 35-15

11/11/21

Types of Lathe

Speed lathe :- It is the simplest of all types of lathe. It is used as wheel, wheel, metal spinning and polishing lathe.

Speed lathe normally do not possess gear box, & energy and lead screw.

Tool is feed manually. Speed lathe is power balance and spindle speed upto about 4000 rpm normally.

Bench lathe :- It is a small engine lathe which can be mounted on a bench. Bench lathe are used for small & light job which require precision.

Bench lathe mostly all the operation are performed.

Engine lathe :- It is a general turning machine. Its main equipment are - the bed, head stock, tail stock, carriage and quill, change gear box.

Engine lathe offers both a speed lathe in terms of additional features of controlling the spindle speed and independently the cutting tool in both, cross & longitudinal direction.

An engine lathe can be driven by an independent

electric motor can be used. Lathe may be driven by an air-chest shaft with the help of belts.

Lathe speed may be changed with the help of cone pulley or through gear shifting. It is most widely used lathe and some times it also referred to center lathe.

A tool room lathe is a tool room lathe which is equipped with additional attachments needed for the tool & die making operation.

A tool room lathe has geared lead stacks with a considerable range of spindle speed from very low to as high as 5500 rpm.

A tool room lathe is usually tested for accuracy and used for making highly accurate, low production work of highly small parts such as test gauges.

A tool room lathe is more expensive than common sizes of the engine lathe.

Turnout and Operation Lathe

It is used for mass production work. These machines are actually of semi-automatic type & very wide range of operation can be performed on them. In operation of these machines very little skill is required. It is well equipped in every in setting of tools & fixtures in turret or repetition feed.

This job of speed is high. They carry special mechanisms for indexing of their stock head.

Front end is seen tool post are available. Tool changing time is less. It has turret head instead of tail stock.

Six different tool can be fitted in turret lathe.

Automatic lathe / special purpose

Working on basis of job is fully automatic. Used for quality & quantity work.

They fall into the category of very cheap. High speed lathe. They are used for production.

Special purpose lathe

It is used for manufacture of those job where exact conformity is produced on normal lathe.

* Some set certain special operators only but more efficiently than a standard lathe.

* Some special purpose lathe are -

→ Gate lathe, Crank shaft lathe, Duplicating lathe, Tracer lathe, facing lathe.

* Cap or Extension type of lathe :-

It is very similar to tool room lathe except that the spur lathe can be adjusted to machine larger diameter work.

The operator can increase the work by moving the bed on distance guard head stock which moves away one or two feet.

By sliding the bed away from the head stock the spur lathe can be used to turn very large workpieces like centers.

* Duplicating lathe :- It carries an amount of area attachment

referred to the carriage which moves along a cam template and guide all carriage. It used for mass production of identical

parts where a precisely machined part parts as a template.

* Facing lathe :-

In this lathe carriage is driven by a separate motor independent of the main spindle. It carries not full stock. It is used to machine end faces of shafts, cylindrical job.

* Crank shaft lathe :-

It carries all attachment like taper turning and threading etc. In addition we can do all support the shaft. It is used for turning long crank shaft etc. a turbine, engine shaft, crank shaft etc.

Basic Parts of lathe :-

- Bed
- Head stock
- Tail stock
- Carriage
- Apron
- Cross slide
- Compound rest
- Tail post

* Tool :-

- It is usually a cutting of iron (cast iron). All the parts of lathe such as head stock,

tail stock etc. are mounted on this bed.

- Cast iron bed ^{only} having very good vibration absorbing capacity but also facilitates on easy sliding motion.

- The bed should be sufficient weight and the spindle material is so that vibration generated during operation are damped out.

- lathe bed are generally rigid.

21/10/20

Head stock

It is a box like casting mounted permanently on the top head side of the bed.

Head stock support the spindle & certain gears are fixed by which work piece may be rotated at various speeds. Spindle is tapered at the nose to have live centre.

Spindle is hollow to exp. except the two flutes and is built into head stock with spindle nose projecting from the bearing of the head stock.

Spindle nose is threaded so that a jaw plate or chuck can be mounted on it to hold the work.

Any correction




Fig:- A threaded spindle nose with a live centre.


→ For making different materials with different tool angles of speed is separated the nose side live provided generally by two different type of head stock.

↳ Belt driven head stock
↳ All geared head stock.

① Belt driven head stock:-
A belt driven head stock comprises a cast-iron step cone pulley and back gear arrangement.

Con pulley on head stock give drive of a gear for spindle speed.

Gears gear cone steel for induction in spindle speed so it provides range of speeds.



Any correction

do span in fig. A locking pin can be used to engage or disengage cone pulley with slack gear.

② All geared head stocks :-

Modern & specially larger lathes incorporate tall gear wheel stock where external steel shells engage with gear wheels.

Great care, the gear wheels are mounted on splines.

In all geared head stock lubrication is very important and it is done by splash.

All geared head stocks can be covered with small oil sump in depth & easy change in speed with jacket openings.

③ Tail Stock

Tail stock is located at right hand end of the bed. It is a cast-rotating part. Chuck can move left & right side of the tail stock to adjust the depth of the work piece.

It is used to support long jobs, it can also be used to adjust about 85mm for cutting small size angle tapered &

usually clamped to any position on the bed. Tail stock is also known as loose center. It consists of cast iron body in which a barrel is located. The barrel is hollow and tapered part with dead center.




Fig:- Tail stock

④ Lathe Carriage

The lathe carriage serves the purpose of supporting, guiding and feeding the tool past of turning the job during the operation on lathe.

The carriage consists of the following main parts - (1) Saddle, (2) Cross Slide, (3) Compound rest on tool post, (4) Apron.

* Saddle - It is the part of carriage which moves along the lathe bed.

and adjust the over slide.

* Over Slide:- It is essential on this type of the saddle and always move a few the perpendicular direction to the cone of the tool as main spindle.

It can either operated by hand or also feed rack or it may be given feed feed by gears mechanism.

* Compound rest:- It is also known as mounted on over slide. It carries a graduated circular disc called Compound plate which allows the movement of the tool along the angular direction not parallel to lathe axis.

It support the tool post. Compound rest does not have any fixed feed.

* Tool post:-




It is the type most part of the carriage. It can hold tool and tool holder. It is mounted on compound slide. It may be of American type, English type or turned tool post.

* Appearance:-

It is the long part in front of carriage at lower end turning for

It is of gear train through which feed can be given to carriage & over slide.

It also carry the double mechanism to apply half nut



Task Holding Devices

Chucks:-

They provide very efficient & true clenching the holding the job a secure grip with little slippage of rotation.

It give consistency. Hence for setting a job as compared to the other.

There are 20 variety varieties in chucks but few of them are given below

① Three jaws (Chiswick Chuck)

It is also known as scroll chuck or self centring chuck. It consists of 3 cylindrical body having three jaws fixed radially at its periphery. In three jaws chuck all the jaws move & simultaneously when chuck is rotated in order to tight up the loose the jaws.

Advantages:-

- Job can be held easily & it is less time consuming
- Extensive range of cylindrical of hexagonal job can be held.
- External & internal jaws are available.

Limitations:-

Only regular round component can be held.




3-Jaw self-centring chuck

② Four jaw chuck

It has not only one mass extra scope to give but also of this jaws can be independently move with respect to each other.

It very regularly give rectangular and circular shapes of the work.



4-Jaw independent chuck

Advantages:-

- Wide range of rectangular & irregular job can be held.
- They can be still concentrically and eccentrically as well.
- High gripping power so heavy cut can be performed.
- Even if the chuck worn out there is no loss of accuracy.

Limitation

- It setting up time is more.
- No job to high gripping give even can be easily damaged.
- Chuck is heavy to set handle on lathe.

① Face plate :-

A metal plate with a flat face that is mounted on the lathe spindle. It holds irregularly shaped work.

A holder necessary for a work on metal turning. The workpiece is clamped to the faceplate. Usually used to machine slots in the faceplate.



② Lathe dog

Also known as ball dog or dog. An L-shaped holder, usually made of cast iron, with a male part. The workpiece and locking tab secure the workpiece. Used to clamp a workpiece and apply rotational force to it while the workpiece is mounted on the lathe spindle.



The dog engages with a slot in the faceplate to apply the force to the workpiece. Used as a means of chucking especially in case the workpiece and when there are not any offsetting the thickness.

③ Collar :- A roller in a multiple of clunk that forms a collar.

Applied on object to be held. It creates a strong clamping force on the object when it is tightened. Usually by means of a tapered outer collar. It may be used to hold a workpiece on a tool.



- Fast clamping, self-centering, strong clamping, resistance against being jacked loose (vibration), precise geometry.

④ Rest (Live and dead center)

Live center Dead center



A precision ground tapered cylinder with a 60° point. It is used to support the end of a long workpiece. The dead center is used to support the workpiece at both ends. The live center is used to support the workpiece at one end. The live center is a center with integral bearing to reduce friction. A dead center has no bearing, so it must be kept lubricated to keep the workpiece and workpiece rotating due to friction.

② Mandrel :-


A mandrel is a round object of soft which material can be forged or shaped on a tool support such as a chuck that grips on sharp material to be working in a lathe can easy after part which will be spin or rotated.



Mandrel are also used in industrial to compare fabrication such as in filament winding. This is manufacturing process, semi-liquid filament are wound around to a mandrel to create a composite structure or parts.

③ Single plate :-

The single plate is a work holding device used as a fixture in metalworking.



The single plate plate is made from high quality material (generally spherical cast steel). It has been drilled to prevent further movement or distortion.

Adjustable single plates are also available for work that need to be finished usually towards a milling cutter.

③ Steady Rest and Follow on Rest ③

Steady rest and follow on rest were developed to remedy the tailstock trailing operation problem. Steady rests and follower rest hold a long work during turning. steady rest are located to the lathe bed and do not move with the lathe. They remove completely but limit the length of the supporting part. Follower rests are to move along with or follow the lathe.




④ Magnetic Chuck ④

Magnetic chuck is another type of holding device. It works on the principle of electromagnetic induction. Magnetic chuck is not suitable for heavy work easy to use and hold the device.



⑤ Lathe Rotation Chuck ⑤

Rotation chuck is the combination of three jaws. You can hold any job of any form of shape. It is used for the job to get robust construction. Skilled workers is required.



Numerical Control (NC) M/C.

NC data medium can be in form of the following functions may be automatic.
 case magnetic tape can switch control/ component of NC lathe M/C system.

Advantage of NC lathe M/C -

- ① Cycle time reduction
- ② Complex M/C operation
- ③ High degree of accuracy
- ④ Less tooling required
- ⑤ Reduction of scrap & rejections
- ⑥ Increase of productivity
- ⑦ Lower tooling cost
- ⑧ Reduction of shutdowns
- ⑨ Greater operation safety

Disadvantage of NC lathe M/C


High investment cost, high maintenance cost, need for skilled programmers & high utilization required.

* Interlocking to CNC lathe M/C (Computer Numerical Control)

are some stored then program and are it any time repeatedly.

* DNC (Direct Numerical Control)


② Feed Mechanism & Change Gears



As G5 gear is shifted it provides

③ Diving Mechanism

* Same pulley & back gears + all gears in lead screw.



* Speed station

→ disengaging position.

Spiral speed = Gear tooth speed \times $\frac{\text{Dia of cutter}}{\text{Dia of stepped cone}}$

* N_1, N_2, N_3 & N_4

Engaged position with blank gears.




Let the mesh speeds are M_1, M_2, M_3 & M_4

Also Speed = Previous Speed \times $\left(\frac{\text{No. of teeth in } 1^{st}}{\text{No. of teeth in } 2^{nd}} \right)$

\times No. of teeth in n^{th} stage

Also Speed = Previous Speed $\times k$

* All gear equal head stock s_0



If S is fixed gear and C is constant we then

1st speed = $S \cdot C$
2nd speed = $S \cdot C^2$

4th gear = $S \cdot C^4$


Now, if n is total no. of speed and N_1 is maximum speed.

Then $N = S \cdot C^{n-1}$
 $\Rightarrow C = \left(\frac{N}{S} \right)^{\frac{1}{n-1}}$

a) $N_1 = \frac{G_1 \times G_2}{G_4 \times G_3}$, $N_2 = \frac{G_1 \times G_4}{G_3 \times G_2}$

12/2013

* Worm Mechanism :-



If in hand wheel for providing longitudinal movement for the lead screw to forwardly lead free to cross slide.

Lead is for engaging disengaging and disengaging the power feed.

Stop wheel is operated when power feed is to be engaged.

Levers in front to close or open the stop wheel out of

inside the spur there are five spindles S_1, S_2, S_3, S_4 to S_5 as named in figure.

Spindle S_1 rotates a gear G_1 at its rear end which meshes with another provided at latter front

Spindle S_2 carries gear G_2 which is operated by lever L_1 . This lever has three position viz. top, or down, or position part in down at fingers F_1 with G_1 meshed on spindle in position 2 gear G_2 is free and mark with any gear. In position 3, top gear G_2 meshes with G_1 .

Spindle S_3 in addition to L_1, G_1 carries another gear G_3 at its rear end. It is always in mesh with gear G_2 which is mounted on the rear end of rear axle.

Spindle S_4 is just below the spindle S_3 . It carries gear G_4 to G_5 in its mesh with G_3 & G_4 is in mesh with rear. However, gear G_4 is not rigidly fixed with the S_4 . It slides with the rear provided it tight on its cone. This gear on spindle S_5 .

The operation when hand feed is required to the given wheel is as follows. In the given wheel whatever the gear G_1 in left kept at down position.

when power feed is the gear at the position L_1 is kept in down position (upward) in that G_2 meshes with G_1 & G_2 meshes with

To give the power feed to the rear wheel the lever L_1 is kept in down position so that gear G_2 meshes with G_1 .

* Working Mechanism of Split Shaft nut

A split nut is a nut that is split lengthwise into two pieces so that its internal thread may be opened and closed over the external thread of a bolt or screw. This allows the nut, when open, to move along the screw without the screw rotating (as with a lock nut). The screw to pass through the nut without drawing). Then when nut is closed, it secures the journal. Movement of a nut on a screw A split nut assembly is often used in positioning systems, for example in the lead screw of a lathe. The two halves of the nut have drawn faces ends (G.I. to axis), which helps the thread to find engagement during the closing action. Split nuts work best with trapezoidal threads.



Internal Threading.

General Cutting Mechanism

37

General cutting in the operation to produce a helical gear is of spur gear style. The V or square can be cylindrical surface.

This can be done by cylindrical surface by forming a machining process. Thread cutting by machine is done by using lathe or other machine thread of any pitch, shape and size can be cut.

Thread cutting on lathe is done by thread cutting steel (single pt). The lead screw thread of pitch pins. The tool must travel a distance equal to pin on work piece and make one complete revolution.

The defect of helical cutting is linear distortion. The top to the bottom is achieved by cutting on impinging the carriage with the lead screw through a screw nut mechanism. A pair of gear station like head stock spindle and tail stock. This is done by using changes gear mechanism or gear box between spindle & lead screw.

The following relationship or word to determine the gear ratio required to generate threads of different pitch.


As contribution

gear ratio = $\frac{\text{Pitch of gear to be cut}}{\text{Pitch of lead screw}}$

38

$$= \frac{\text{Lead of gear to be cut}}{\text{Lead of lead screw thread}}$$

$$= \frac{\text{No. of teeth of driver (cutting gear)}}{\text{No. of teeth of driven (lead screw gear)}}$$



All the lathe etc are provided with a set of change gear usually having 20 to 120 with variation of few teeth in addition a gear of 127 teeth is all provided which is known as planetary gear screw in metric threads.


After determining of above gear ratio the next step is to select the suitable gear. The numerator & denominator of fraction of gear teeth are to find out the ratio of teeth of the change gears.

There are two types of gear train are employed in cutting thread.

As contribution

(A) Simple gear train (B) Compound gear train

Simple gear train consist of drives gear mounted on shafts of shaft gear mounted on shafts and one or more intermediate gear. Intermediate gear have no effect on gear ratio.



A compound gear train consist of two shafts not started instead of one. Each gear train is employed when desired gear ratio is such that it is not possible to arrange by simple gear train out of the given set of change gears.

Ques: Calculate the change gears to cut PI thread of 8mm pitch on a lathe having lead screw pitch of 6mm pitch.

Relations gear ratio = $\frac{2}{6} = \frac{1}{3} = 1:3$

Change gear = $\frac{1 \times 20}{3 \times 20} = \frac{20}{60}$ Driver teeth
 20 → Driver teeth
 60 → Driver teeth

Ques: Calculate the change wheel to cut thread of 1mm pitch on a lathe having lead screw of 8mm pitch.

Relations G.R = $\frac{1}{8}$

Change gear = $\frac{1 \times 20}{8 \times 20} = \frac{20}{160}$ (not possible)

= $\frac{1 \times 40}{8 \times 40} \Rightarrow \frac{40}{320} \times \frac{20}{80}$
 compound by driver

* Cutting Metric Thread on English Standard lead screw as well as

Many times it may be suggested to cut standard lead screw in the lower massing its pitch in inches by such case the following relations will help -

Driver = $\frac{5}{127} \times \text{Lead of screw to cut}$
 Driven = 127 (Lead of thread on lead screw in inches)

The case of reverse requirement that is when diameter of British standard pitches are to be cut on lathe having lead screw in metric pitch.

Driver = $\frac{25.4}{\text{Lead of screw in inch}}$ and in inches
 Driven = 25.4 (Lead of thread on lead screw in mm)

ques Calculate the change gear for cutting a gear
not having any standard thread of outside
pitch on like having lead screw of 8mm
lead.

Solutions

$$\frac{\text{Driver}}{\text{Driven}} = \frac{127}{5} \times \frac{0.5}{8} = \frac{127}{5} \times \frac{1}{16}$$

$$= \frac{127}{5} \times \frac{1}{32}$$

$$= \frac{127}{5} \times \frac{1}{(4 \times 8)^2}$$

$$= \frac{127}{50} \times \left(\frac{1}{2} \times \frac{20}{20} \right)$$

$$= \frac{127}{50} \times \frac{20}{10}$$

Operations of an lathe M/C

All the operation can be performed on lathe
can divide into two groups

Standard or common operation

They include: ^{turn} face, step turning,
facing, taper turning, drilling, reaming,
boring, turning, threading, etc.

Special or special operation

They include grinding, milling, tapping,
lathe electrically, spinning etc.

* Plane and Slip turning:-


Both of these operation
are simple operation and can be done by
hands in job in many different ways
Also they can be done:-

- > on four planes plate
- > in a few hands
- > on mandrel

Turning of a conical:-

In turning operation one end of the job is
held in V block of dog usually and
on other end is supported by the turn
of live centres the other end of the
job is supported on the dead centre.

W/C in between actually the operation as
taken the job in cement to driving plate
to the lathe tool is fed again this job
is shown in fig.



Carrying a liberty of centre is very important
and during this turning operation accuracy of
centre is done by giving, self parallel of
combination set, snap gauge etc.

Turning on faces flat on chert :-

Face flat is usually cylindrical, round and round eccentric jobs and to be supplied when cannot be easily held on chert. Work even be done on face plate chert on rolls. The shape of chert flat, and convex depending upon the shape of the job.


Well designed fixtures are also used for cherting the job in operation with face plates when from production with face some jobs are required on job and in odd shape.

Holding of job in these operation is done by one bar in case from jaw independent. In the proper way in case. The diff. methods are shown for sensory. Still job are as follows.

- ① clamp chert method :-
- ② barner method
- ③ dial method

Tips And Fixture

* Cherting of turning tool :-



* Rough and finish turning :-

For heavy stock removal in order to pass maximum time, in this turning done out a heavy feed is taken.

⇒ finish turning is after rough turning from start to close to the turning operation. Small is step depth of cut in wheel.

* Tapper turning :-

For several passes the chert. This also of these work use known as tapper or face plate. Price the chert. This work on change. Precision of these work and in known as tapper.

Face/Tooling may have integral or separate. It happens according to the requirement.


This is a common method of expanding tapper.

- are -
- 1) Topper for flat
 - 2) Topper for thick
 - 3) Topper for thin
- * Standard topper

A ~~type~~ no. of topplers series have been standardized which are commonly used. Most common of them are as follows:-

- 1) Horse-topper \rightarrow (4/8 inch per foot length)
- 2) Brown and Sharp toppler (1/2 inch per foot)
- 3) Fox Tanno toppler (1/8 inch per foot)
- 4) Metric toppler (mm per suit length)

For conical toppler:-



* Total toppler = $\frac{D-d}{2L}$

Methods of topper turning:-

- 1) Tail stock set over method
- 2) By travelling the compound rest.

- 1) Why the topper turning starts at slackness. (in form or bend. more tool.)


* Tail stock set over method:-

During the topper turning on a job the work is rotated and the tool is fed out the of cutting tool should move on at an angle to the work line of the job. This inclination should be equal to the sine of the total topper angle. There can be two methods for accomplishing this job.

- 1) The job remains in position while steel moves along the straight line which is inclined to an angle α to the center line of the job.

2) An alternative method is that it can be shift the center line of the job at an angle α from the original position parallel to axis of spindle.

In second method it is observed that over the the tail stock the this distance between the part of the tail stock. This distance is given by means of set screw provided on both front & rear of the body of the tail stock. Since the deal center is shifted from original position to new determined amount get over.



From the figure; $x = 1.5$ inch, as it is relatively small, then it can be neglected as -

Since $x \ll \text{Len}$

So $x = 1.5$ inch

$$x = L \times \left(\frac{D-d}{2L} \right)$$

$x = \text{Total length} \times \text{Tail taper}$
or $x = \text{Tail taper length}$

The error of full length taper $\Delta L = 1$

$$x = \frac{D-d}{2}$$

Ques: Calculate the amount of offset of the tail stock for turning taper on full length of a job of a round bar which have the two diameter of 4 inch & 1.5 inch respectively.

$$x = \frac{D-d}{2} = \frac{4-1.5}{2} = 0.85$$

Ques: Sketch the tail stock set over for turning a taper on a job with about its two diameter same. Power good form. Total length of the job is 10 inch & the taper is 1:100.

$$x = L \times \left(\frac{D-d}{2L} \right)$$

$$x = 10 \times \left(\frac{20-60}{2 \times 100} \right)$$


$$x = 15 \text{ mm}$$

Q By skimming the compound rest/compound rest set by grid method

Skim taper was set by setting the compound rest at an angle and level factory using the compound rest screw.


The compound rest on lathe has a circular base which is rotating. This is done by rotating the compound rest the job. There are a dial indicator in the center on circular plate which helps in early setting of angle during taper operation.

It is very easy method but must length can be cut only if it is about 75-100 mm.



$$\alpha = \tan^{-1} \left(\frac{D-d}{2L} \right)$$

③ By using tapping tooling attachment



⇒ In this method special attachment for tapping in place of the rear end of the drill bit. The attachment also has part, one thin guide block which is parallel to both tool & the ground surface. Movement in angular direction. The screw starts with free form screw. By using this cutting drill can be guided through out the length when has to be tapered.

Advantages:-

Easy & quick setting.
 Tool is no requirement of high skilled labor.
 Very strong, tapping on soft work possible.
 It provides better surface finish.

③ By using a broad nose form tool

In this method of tapping using a broad nose tool having straight cutting edge is not due to the chip cut (cutting) angle with the help of this method the taper of short length can be tapered.

④ Facing :-



Facing is done at the end of the job. It is a process of cutting a face which is a planar surface, with the workpiece.

⑤ Chamfering :-



It is a process of end edge removal of the job.

⑥ Grooving :-

A long, narrow cut or indentation in a surface, on the cut by a special tool removes the form of another small.

Dr $\alpha \approx 60^\circ$ ✓ 50

③ Fluting :- Fluting is the process of cutting of grooves of flutes outside of a long hole in the lathe. This process gives an especially disposed tool bit with cutting edge similar to that of a square.

④ Drilling :- Drilling is a cutting process that uses a drill bit to cut a hole of various cross-section in a work material.


⑤ Reaming :- In reaming, boring in the process of enlarging a hole that has already been drilled by means of a reamer - kind of cutting tool.

⑥ Milling :- Milling is a manufacturing process typically conducted on a lathe, whereby a pattern of straight, angled or grooved lines is cut or milled into the material.

⑦ Forming :- Forming processes are particular manufacturing processes which make use of plastic stresses to cause plastic deformation of the materials to produce required shapes. In forming processes no material is removed.

N → Speed of job in rpm.
 n → no. of passes.
 L → Total distance in mm

Calculation based on speed, feed and depth of cut:-



When a job is turned on lathe after considering the above fig. t can be written as

$$t \text{ (min)} = \frac{D \cdot L}{v}$$

and the cutting speed which is defined as distance traveled per minute by a point on the circumference of the work in direction parallel to the direction of feed.

This speed can be calculated by the following relationship -

$$V = \frac{\pi D N}{1000} \times \frac{60}{30} \quad \text{or} \quad V = \frac{\pi D N}{30} \quad \frac{\text{m/min}}{\text{rpm}}$$

where, V = cutting speed in m/min

D = diameter in mm

N = rpm

Ques) Determine the initial speed in rpm of rotation during cutting at speed of 150 rpm

In 10 min from it can be written in diagram travelled by the tool in direction of feed

$$L = d + 1/4 \cdot d \cdot e$$

If there is a frame then total distance travelled by tool can be written as

$$L_1 = L \times N$$

also the speed of feed per minute can be calculated by the following relationship

$$f = f_1 \times N$$

$f_1 \rightarrow$ feed in mm per revolution

So, the time in minutes required for the tool to move through the length L can be written as -

$$T = \frac{L}{f} \text{ minutes}$$

$$T = \frac{L \times N}{f_1 \times N}$$

\rightarrow A hollow cup of 10 mm outside dia and 150 mm length in shell on a vertical span cutter and turned all over in four passes by the approach length in 30 mm and can travel in 12 mm. Answer required to 0.8 mm/revolution

cutting speed is 30 m/min. Calculate the cutting time.

$$T = \frac{L \times N}{f_1 \times N} \quad V_c = \frac{1000 \times \pi \times D \times N}{1000}$$

$$f = f_1 \times N = 0.8 \times 159.2 = 127.324 \quad N = 159.2$$


$$T = \frac{150 \times 159.2}{127.324} = 182.24 \text{ min}$$

$$\text{Total } T = 182.24 + 12 = 194.24 \text{ min}$$


$$T = \frac{182.24}{127.324} = 1.43 \text{ min}$$

Shaper Machine

(Tool → SS)




* PLANNER *



Slotting Machine (Slitter)

(Tool ↓ SS)



Machining time for Shaper

Let 'l' be the length of stroke (m) of shaper

where 'l' includes tool clearance at both ends

Let V_c = cutting speed (m/min)

V_r = return speed (m/min)
 f = feed per stroke, in mm

∴ time for cutting stroke (t_c) = $\frac{\text{length of stroke}}{V_c}$

again time for return stroke (t_r) = $\frac{\text{length of stroke}}{V_r}$


Total time for one-cycle (T) = $t_c + t_r$

Now if 'N' is width of chip with clearance included either side then no. of stroke cycle required = $\frac{N}{f}$


∴ the machine time for whole job (T_m)

$$T_m = \text{no. of cycle} \times \text{Total time}$$

$$= \frac{N}{f} \times T$$



Ques: Calculate the time to machine 250 mm long plate 100 mm wide. Tool clearance at each of stroke is 30 mm & 20 mm respectively. Cutting speed is 10 m/min, return speed is 20 m/min. Assume an alloy steel with a distance of travel in width direction is 10 mm, and



$$l = 250 + 30 + 30 = 310 \text{ mm}$$

$$W = 100 + 10 + 10 = 120 \text{ mm}$$

$$t_c = \frac{310}{10 \times 60} = 0.517 \text{ min}$$

$$t_r = \frac{100}{20 \times 60} = 0.833 \text{ min}$$

$$\text{Total time} = 0.945$$

$$T_m = \frac{W}{f} \times T = \frac{100}{1} \times 0.945 = 94.5 \text{ sec}$$

Ques: A chip 100 mm wide requires one cut. The cutting speed is 1000 cm/min. A return speed is in ratio of 0.1. The job is 15 mm from cutting stroke. How long will the chip take to get done?

$$V_c = 1000 \text{ cm/min}$$

$$\frac{V_r}{V_c} = \frac{1}{10}$$

$$V_r = 100 \text{ cm/min}$$

$$T_c = \frac{100}{1000} = 0.1 \text{ min}$$

$$T_r = \frac{100}{100} = 1 \text{ min}$$

$$T_m = 1.1 \text{ min} = 66 \text{ sec}$$

* Milling Machine *

Milling is a machining process in which removal of metal takes place due to the rotating multi-point cutting tools. In milling process tool is in rotary motion and the job is fed against the rotating tool.

It is generally used for small & medium sized jobs.

A large variety of machining operations can be performed.

→ Working principle :-




A milling machine is a power driven machine for metal in cut by means of multi-point cutting tool by feeding the work against the rotating cutter.

The optimum cutting speed can be achieved by selecting proper cutter design, suitable type, quantity, & performance wear holding fixture design.

On the other way a span small and medium metal job with the help of milling machine is very economical way of milling machine.

It is mounted on table of the column and used for support the work with the help of yoke.



① Column :- Horizontal column & knee type M/C

It is mounted on table of the column and used for support the work with the help of yoke.

② Table :- It contains T-slots mounted on top of the table saddle and hold the w/p

③ Knee :- It contains feed change gear & mounted on saddle with the wear adjustment by screw down.

④ Saddle :- It provides

⑤ Base :- It heavy casting of cast iron, cast on sandstone and support the column & knee jack.

Q) Column:- It is main part of milling. It supports various gears and contact with the gear mechanism, drive mechanism & electrical part etc.

At its top its support over arm.

* Types of Milling machines *

(A) Column and knee type milling m/c

(i) Hand milling m/c
It is simplest & simplest of all milling m/c. All the operations such as cutting of gears are performed by hand.

Usually it is used for small components milling like hexagonal or square heads on bolts, nuts, cutting slots, cutting of keys ways etc.

(ii) Knee horizontal milling m/c

It is very common milling m/c. It is having a table horizontal position that why it is named as horizontal milling m/c. These tables serve as primary gear electrical, main drive & spindle etc.


There are also a support for addendum work table and other accessories like indexing table etc.

The table can be given straight motion in three direction - horizontal, vertical, & longitudinal, but cannot be swivel.

(iii) Vertical milling m/c.

In this m/c due to vertical position of spindle

These m/c are available in both horizontal fixed head type & vertical type & column type.



The main part of it is work's removability. Head,

in this m/c "we are" an integral part of it & having a fixed or swivelling head at its front end.

In this fixed type head, tool moves in only up & down direction whereas in swivelling head it can be move in regular direction too.

Mostly used in face milling operation.

* (iv) Universal milling m/c

A milling machine having or table fitted with all features and a dividing head with change gears so that it can perform any

Types of Milling operation.

(B) Fixed bed type or Manufacturing type

i) Fixed bed plain milling :-

- It differs with column

& knee type of milling

in the absence of space

in mounted -

instead of saddle & knee

- This cannot move up & down on even in same work direction

- Spindle rotation in spindle head can be moved by adjusting the table to the work




Fig: Fixed bed plain milling

ii) Double head fixed bed type milling :-

It is another method

of fixed bed type

milling machine

two spindles head

or rotation can

be made up to spin

direction along the

column simultaneously

or individually.




Fig: Double head fixed bed type milling

(iii) Planer type milling machine :-

A planer is a type of metalworking machine

tool that use linear relative motion

the workpiece and a single-point cutting

tool to cut the workpiece. A planer

is similar to a shaper, but larger and

with workpiece moving in a

shaper and cutting tool moves.

Application - Generally used for surfaces


cutting at large

(c) Production type or continuous milling M/c

This type of m/c are used in mass production of any component and with substitution of any metal and subject and the process is continuous in its ideal form.

It has three time more production rate than the slow 'milling' m/c. It also requires less space.

Example:- turn down type milling, planetary type, base type milling m/c, vertical



(d) Special purpose milling M/c

When milling m/c are design for particular or specific purpose then this category belongs to special purpose milling m/c. They may be used for greater accuracy, long better finish or run other purposes like circular motion of cutting tool.

6/9/2020

Some special purpose milling m/c are -

- 1) Thread milling m/c
- 2) Gear milling m/c
- 3) Planetary milling m/c



Sybil M

6/9/2020


Date
27/3/2017

* Milling machine attachment *

- To hold the cutter - Arbors, Collets, shapers etc.
- To hold the work piece - Vices, Clamps, Tables, vices, head rail stock etc.
- To work on auxiliary spindles - Vertical, Milling attachments, special milling, milling attachments etc.

* Milling methods * Milling can be performed by two methods -

- 1) Up or conventional milling.
- 2) Down milling.



Up:-

→ The cutter rotates in direction opposite to that in which the work feeds are fed.

→ Chip thickness increases from the start of cut and point of cutting.

→ Use for setting and forging.

* Down

In this milling operation with direction &

work feeding operation since it is a

3 Chip thickness clearance from tooth to work and out of it.

3 This milling method is used for the finishing operation of small finisly surfaces

* Cutting speed & feed *

→ Cutting speed :-

Cutting speed of milling rate is the distance travelled / minute by cutting edge of the cutter. It is expressed in m/minute or feet/minute or depending upon the unit adopted.

Also, surface that is cut is the dia of the cutter and it makes 11-revolutions per minute.

So, distance travelled by the cutter in one revolution = $\pi D \text{ mm}$.

So, $\pi \times \text{dia.} \times 11\text{-revolutions}$ = distance travelled = $\pi D \times 11 \text{ mm/minute}$

Cutting speed = $\frac{\pi D \times 11}{1000}$ m/min or

= $\frac{\pi D \times 11}{12}$ feet/minute

Q. If millly cutter room dia sum of its speed calculate the cutting speed.

→ Feed :-

It is distance travelled by the table in any direction (mm). Feed can be given to table by hand or automatic machine.

Feed can be expressed in three following ways -

- (i) Feed / minute
- (ii) Feed / tooth
- (iii) Feed / revolution.

→ It is table travelled in one minute in any direction (mm/min.)

→ It is table travelled in mm during the one period of angular travel of tooth. Accordingly distance upto the cutting edges of two adjacent teeth. (Feed / tooth)

→ It is table travel in mm during the period of cutter one full revolution.

Note :-

Feed/revolution = Feed/tooth x T where, T = no. of teeth

Feed/minute = Feed/revolution x N = Feed/tooth x T x N

* Estimation of milling time *

Factors for milling time

- ① Total length
- ② Approach
- ③ Cutter diam
- ④ Number of cut
- ⑤ Cutting speed
- ⑥ Feed per minute

→ Total length :-

It is the length of the job to be cut

→ Approach :-

It is distance to move the cutter before reaching the full depth of cut

→ Over run :-

Distance moved by cutter after the job length to be done of the job

* Also considered milling operation on plane & face milling :-

→ Plane milling operation :-



→ Plane milling operation



It is length to be cut, L_1 is approach length and L_2 is over run in mm. Then total length covered by the cutter -

Total length travelled by cutter [L]

$$L = L_1 + L_2$$

In series of plane milling

$D \rightarrow$ cutter diameter
 $d \rightarrow$ depth cut

$$\text{Then } L_2 = \int d (D-d)$$

→ face milling operation :-



Let d_1 be the width of job and d_2 be the cutter diameter.

Then $d_2 = 0.5 [d_1 + \sqrt{d_1^2 - b^2}]$

The over runs of the cutter depending upon the size of work surface can be taken as 1-6 mm.

Here, if 'n' be the no. of cut only of feed in mm/min. Then the milling time (T) =

$$T = \frac{n \times L}{f}$$

min.

Note :- For finding out the total planer time, chewing time should also be added to the actual planer time.

* Milling Cutters *

(1) Inverse relation vice and cone must be maintained for set screw.

(2) Constantly observe how wearing type of operation with different cutters and adjustment.

* Miller Cutters materials *
- cutting quality, days in operation, shape.

- Harder than metal being machined.
- Resist heat & abrasion of cutting.
- Most order of

High speed steel :-
Carbide - carbide :-

Classification of milling tool

- (1) Plain milling cutter
- (2) Angle milling cutter
- (3) End milling cutter
- (4) Formed milling cutter
- (5) Face milling cutter
- (6) Woodruff key milling cutter
- (7) High speed steel cutter
- (8) Carbide cutting cutter
- (9) Flat slot milling cutter
- (10) Plain finishing cutter
- (11) Metal turning cutter
- (12) Metal turning cutter
- (13) Metal turning cutter
- (14) Metal turning cutter
- (15) Metal turning cutter
- (16) Metal turning cutter
- (17) Metal turning cutter
- (18) Metal turning cutter
- (19) Metal turning cutter
- (20) Metal turning cutter

- (1) Light duty plain milling cutter
- (2) Heavy duty plain milling cutter (Helix & us)
- (3) High helix plain

(4) Side milling cutter (straddle milling)

- Half side milling cutter
- plain side milling
- stragel

(5) Face milling

- Shell type milling cutter
- Formed cutter
- Concave
- Convex
- Open Tooth

(6) Angular milling cutter

Milling operation


Geometrical milling

- ① Slab milling
- ② Slotting
- ③ Straddle milling
- ④ Slitting (divided the two ^{one} work into two part)

→ Face milling (cutting to 1 tooth machine tool surface)
 - High production rate
 - Requires significant forces.

→ End milling
 End mills with flat ends (so called square-end milling)

→ Pocket milling



Another form of end milling used to mill shallow pockets into flat parts

→ Angular Milling - Horizontal milling machine

→ Gang Milling

→ Slot Milling



→ Milling of complex surfaces

INDEXING

By indexing we can division of job finally into few divided one by equal division of in done by horizontal movement of the work over that the job surface through a definite angle after one cut in over.

It is possible to divide the periphery of work into any one of equal parts.

→ There are generally three types of head is used to perform indexing.

- ① Plain dividing head
- ② Universal dividing head
- ③ optical dividing head

By indexing

The following methods of indexing are commonly used:-

① Worm or simple indexing

Plain indexing involves the use of crank worm wheel, and index plate. Worm wheel carries no teeth and worm is made of spindle.

Since, the worm has angle starts direct and

and the resin used also to turn the ^{with} those
turns of work the main wheel rotates through
one pitch. i.e. to 1 revolution.

Thus, the work will have to rotate
through 30 turns in order to rotate
the work through one complete turn.

The holes in the wheel plate serve to
sub-divide the rotation of work.

Given: $\frac{40}{N} = \frac{1}{30}$ no. of divisions

In case of fraction, the numerator denotes
the no. holes to be moved by the work and
denotes the no. holes of on the circle to be
be used.

Ques 3: If we required to divide the length of job
into 30 equal divisions find the work
movement.

Work movement = $\frac{40}{30}$

= $\frac{40}{30} = \frac{4}{3} \times \frac{6}{6} = \frac{12}{18}$

Ques 3: Required 30 divisions on a plate for the
efficiency plate movement.

Compound Indexing:

This method employed when no. of division
is required in regard the work of simple
indexing.

It involves two repeat movement by turning
the work or different amount in one
direction.

By turning the index plate and work
both either in same or reversed
direction.

Procedure :-

1. Factorize the no. of division required.
2. Factorize the stock of no. of teeth.
3. Select for the first gear two circles on
the same plate and on its same side,
factorize the no. difference
circle.
4. Factorize the no. of holes on the other
circle.

After finding the above values place all
of them in following way.

Factors of division required x factor of the
diff. of teeth hole circle

Factor of no. x factor of first circle x
factor of 2nd circle

Case

78
19

① If the above expansion gives one multiplication indicates the value selected was correct

If not then repeat the process.

If the series then the required underlying movement will be $\frac{a}{b} - \frac{x}{y}$

$$\frac{ax}{by} = \frac{x}{y}$$

where a, b denotes no. of holes in two circle

The positive parts of the two indicates the movement by which in same direction in the path shows the movement of the plate and same in opposite direction.

② After fixing the above expansion calculate $\frac{ax}{by} + \frac{x}{y} = \frac{ax+yb}{by}$ no. of divisions required

③ Calculate the compound identity for 27 divisions

